

STATE

COUNTY

TOWN OR VICINITY

New Mexico ✓

Taos

Ranchos de Taos

1p

INDEX NUMBER

MONUMENT

NM, 28. RANTA, 5-

Typical roof construction - adobe house

REPRESENTED IN
NEGATIVE FILE

H.A.B.S. SURVEY NO.

N.M. - 42

Cross section of adobe house being
demolished, showing typical mode
of construction with adobe walls,PUBLISHED
PHOTOGRAPHSplastered inside and outside with adobe mud,
the inside having finish coat of whitewashPUBLISHED
DRAWINGS(yeso) ceiling logs (vigas) smaller cross logs
(sabinos), twigs and brush with adobe soil
fill for roof. The spouts (canales) shown
are of sawed plank. A typical canale would
be a short log gouged out on top to form the
trough.✓
102

Author of card

Trent Thomas, 236 Johnson St., Santa Fe, New Mexico

April 9, 1940